



Up-to-date Questions and Answers from authentic resources to improve knowledge and pass the exam at very first attempt. ---- Guaranteed.



AMPP-FIS MCQs  
AMPP-FIS Exam Questions  
AMPP-FIS Practice Test  
AMPP-FIS TestPrep  
AMPP-FIS Study Guide



[killexams.com](http://killexams.com)

**AMPP**

**AMPP-FIS**

*Fireproofing Inspection Specialty*


ORDER FULL VERSION



<https://killexams.com/pass4sure/exam-detail/AMPP-FIS>

**Question: 759**

A fireproofing contractor is performing repair work on IFRM that was damaged by mechanical impact during construction. The damaged section measures 24 inches × 36 inches with material loss ranging from 0.3 inches to 0.8 inches in depth.



The contractor proposes applying new IFRM directly over the damaged area with a 2-inch overlap onto the surrounding undamaged material. The original specification called for 1.75 inches of IFRM thickness. What critical issue must the contractor address before applying the new material?

- A. The contractor must apply a new primer coat to all exposed surfaces including the undamaged IFRM overlap area to ensure chemical bonding of the new material
- B. The contractor should grind the damaged area to create a uniform depth before applying primer and new material to achieve consistent final thickness
- C. The contractor should apply the new material without primer since the existing IFRM surface will provide adequate mechanical adhesion through the overlap
- D. The contractor must remove all loose material and feather the edges to create a smooth transition, but primer application is only necessary on bare steel surfaces

**Answer: A**

Explanation: When repairing IFRM damage with overlap onto existing undamaged material, primer application to both the bare

substrate (where material was lost) and the overlap area of undamaged IFRM is critical for achieving proper chemical bonding. The new IFRM formulation requires a compatible primer to establish adhesion; applying material directly to the existing IFRM surface without primer significantly increases the risk of delamination at the interface between old and new material. While loose material must be removed and edges should be prepared, the primer application is not limited only to bare steel—it must extend across the entire overlap zone to ensure uniform bonding. Grinding to uniform depth, while potentially beneficial for aesthetic purposes, is not the primary critical issue; the chemical bonding through proper primer application is the essential requirement for repair durability. The 2-inch overlap provides adequate coverage area for the repair, but only if the primer is correctly applied to all substrate surfaces.

**Question: 760**

ASTM E605 density test frequency for beams/girders/columns per IBC: one sample per type per:

- A. 2,500 ft<sup>2</sup> or portion in each story
- B. Entire floor regardless of size
- C. 10,000 ft<sup>2</sup> floor area
- D. Only high-density areas

**Answer: A**

Explanation: IBC 1705.15.5 requires one density sample per structural member type per 2,500 ft<sup>2</sup> or portion thereof in each story, ensuring comprehensive coverage.

**Question: 761**

A structural assessment specifies that a column must retain at least 70% of its yield strength during a design fire. Test data provide strength retention values of  $R_T = 0.8$  at 450 °C and  $R_T = 0.6$  at 520 °C. If the protected column is predicted to reach 500 °C at 90 minutes, what is the likely risk relative to the 70% retention requirement?


- A. The column always retains more than 0.8 strength at any temperature below 600 °C
- B. The requirement is irrelevant once temperatures exceed 400 °C
- C. The column likely violates the requirement, because at 500 °C the strength retention is probably between 0.6 and 0.8, below the required 0.7
- D. The column clearly satisfies the requirement because  $R_T$  is still 0.5 at all higher temperatures

**Answer: C**

Explanation: With known retention of 0.8 at 450 °C and 0.6 at 520 °C, interpolation suggests retention at 500 °C is below 0.7, indicating the column will not meet the 70% strength requirement if it reaches that temperature.

**Question: 762**

A fireproofing inspection reveals that metal lath mesh used to mechanically anchor SFRM to structural steel has corroded significantly in a localized zone measuring 8 feet × 3 feet on a building exterior wall.



The SFRM above the corroded lath shows surface crazing and minor delamination affecting approximately 15% of the lath area. The fireproofing thickness in this zone measures 1.6 inches, which is 0.1 inches below the 1.7-inch specification. What is the primary structural concern and recommended remediation?

- A. The corroded lath has lost approximately 40% of its mechanical holding capacity; the affected SFRM section must be removed and reapplied with new lath to restore full fire protection integrity
- B. The lath corrosion indicates the presence of chlorides that will continue to corrode the underlying steel substrate; the affected SFRM must be removed, the steel cleaned, and new lath and SFRM applied
- C. The corrosion is a cosmetic issue limited to the lath surface and does not affect fireproofing performance since the SFRM thickness remains above 1.5 inches minimum
- D. The minor delamination and thickness deficiency can be addressed through localized patching with new SFRM material without disturbing the corroded lath

**Answer:** A

Explanation: Metal lath serves as the mechanical "key" that anchors fireproofing to steel substrates. When lath corrodes, it loses cross-sectional area and mechanical strength, reducing its capacity to support the fireproofing material and resist mechanical stresses. The 60% surface corrosion visible in this inspection indicates substantial loss of lath integrity—estimated at 40% reduction in holding capacity. While the SFRM thickness of 1.6 inches remains above absolute minimum (1.5 inches), it falls below the specified 1.7 inches, and the combination of corroded lath, surface crazing, and minor delamination indicates the fireproofing system is compromised. The presence of corrosion suggests moisture has penetrated to the lath level, but the primary concern is mechanical failure of the lath's anchoring function. Patching without addressing the lath will not resolve the underlying mechanical deficiency. Complete removal and reapplication with new lath is the appropriate remediation because it restores the full mechanical bond required for long-term fire protection performance. The corrosion pattern suggests chloride exposure, which warrants investigation of the chloride source, but the immediate remediation priority is restoring the mechanical anchoring system.

**Question:** 763

Rigid board encasement on atrium trusses reveals incomplete sealing at penetrations. For 120-minute cellulosic rating, what is primary implication?

- A. Improves cooling via ventilation
- B. Only smoke resistance affected
- C. Penetrations self-seal under exposure
- D. Unsealed penetrations create heat bypass paths, reducing effective protection to 60-90 minutes

**Answer:** D

Explanation: Encasement integrity depends on sealed penetrations; openings allow convective/radiative heat transfer directly to steel, dramatically reducing insulation time in ASTM E119 conditions.

### Question: 764

An inspector is establishing a Bayesian Sampling protocol for thickness verification on a 200,000 square foot structural steel project. Prior inspection data from similar projects indicates a baseline non-conformance rate of  $p_{\text{prior}} = 0.08$ . After inspecting 45 randomly selected locations, the inspector observes 2 non-conforming measurements. Using Bayesian methodology, what is the posterior probability estimate for non-conformance, and what sampling frequency adjustment should be implemented?

- A. Posterior probability is 0.089; maintain current sampling frequency of every 2,500 square feet
- B. Posterior probability is 0.067; increase sampling frequency to every 1,500 square feet
- C. Posterior probability is 0.102; implement intensive sampling at every 1,000 square feet
- D. Posterior probability is 0.044; reduce sampling frequency to every 5,000 square feet

**Answer:** D

Explanation: Using Bayesian updating with a Beta-Binomial conjugate prior model, the posterior probability is calculated as:

$$p_{\text{posterior}} = \frac{p_{\text{prior}} \times L(\text{data}|p_{\text{prior}})}{p_{\text{prior}} \times L(\text{data}|p_{\text{prior}}) + (1-p_{\text{prior}}) \times L(\text{data}|p_{\text{alt}})}$$

With observed data showing 2 non-conformances in 45 samples (observed rate = 0.044), the posterior probability converges toward the observed rate while incorporating prior knowledge. The calculation yields approximately 0.044, indicating that observed performance is better than the prior baseline. This lower posterior probability of non-conformance justifies reducing sampling intensity. When posterior probability decreases below the prior baseline, sampling frequency can be reduced proportionally. A posterior of 0.044 (44% improvement from prior) supports reducing sampling from 2,500 to 5,000 square feet per sample location, representing a 2x reduction in sampling density. This adjustment reflects the Bayesian principle of updating confidence based on observed evidence while maintaining adequate verification coverage.

### Question: 765

A contractor applies cementitious SFRM to a W14×90 beam under UL Design N607. The product data sheet specifies a volume solids of 68%. During application, wet film thickness (WFT) measurements average 1.8 inches using a notch gauge. What is the expected minimum average dry film thickness (DFT) assuming no significant shrinkage?

- A. 1.22 inches
- B. 1.44 inches
- C. 1.08 inches
- D. 1.80 inches

**Answer:** A

Explanation: DFT is calculated as WFT multiplied by the volume solids percentage. Here,  $DFT = 1.8 \text{ inches} \times 0.68 = 1.224 \text{ inches}$  (rounded to 1.22 inches). This conversion is essential for inspectors to verify in-field application aligns with UL Design N607 minimum thickness requirements before curing, as excessive evaporation or improper mixing can reduce final DFT below the listed

value needed for the fire rating.

**Question: 766**

You inspect SFRM applied directly over a steel beam that was left with a tightly adhering shop-applied alkyd coating. The SFRM manufacturer's literature states "apply only to bare steel or approved primers listed for this product." No UL documentation lists this alkyd as acceptable. What is your determination?

- A. The installation is acceptable if WFT meets specification
- B. The installation is acceptable because alkyds are non-combustible
- C. The installation is acceptable if density tests pass
- D. The installation is non-compliant because the substrate/primer combination is not approved for the SFRM in the UL design or manufacturer documentation

**Answer: D**

Explanation: Substrate/primer compatibility and listing are critical; using an unapproved alkyd coating beneath SFRM deviates from the tested system and invalidates the UL-based rating.

**Question: 767**

In a performance-based design for a warehouse, engineers allow for partial burnout of the roof purlins, which are protected only for 60 minutes, while the main frames are protected for 2 hours. The analysis shows that after 60 minutes, loss of purlin capacity does not lead to global collapse if the main frames remain below 538 °C for at least 120 minutes. During inspection, you find main frame fireproofing thicknesses are consistently 15% below the specified value. What is the most critical concern regarding the global fire resistance of the structure?

- A. Reduced main frame protection may cause these members to reach critical temperature earlier than 120 minutes, invalidating the global stability assessment
- B. The difference in thickness is negligible compared to the purlin failure sequence
- C. The main frames will always stay cooler than purlins and thus remain safe
- D. Only purlin protection matters, since purlins fail first

**Answer: A**

Explanation: The performance-based design relies on main frames maintaining strength for at least 2 hours while purlins are allowed to fail earlier, so a 15% reduction in fireproofing thickness on the main frames can significantly shorten the time it takes for them to reach 538 °C, undermining the assumed fire resistance and potentially compromising overall stability.

**Question: 768**

A building's structural steel is protected with intumescent paint applied to a thickness of 0.10 inches. During a fire scenario analysis, the engineer calculates that the paint will expand to approximately 0.75 inches of char during fire exposure. The steel's critical temperature is 1000°F. If the char layer has thermal conductivity of 0.08 BTU/(hr·ft·°F) and the fire temperature reaches 1800°F, approximately how long would it take for heat to conduct through the char layer to the steel surface, assuming the outer char surface reaches fire temperature? Use:  $t = \frac{\rho \cdot c \cdot d^2}{\pi^2 \cdot k}$  where  $\rho = 8 \text{ lb/ft}^3$  (char density),  $c = 0.3 \text{ BTU/lb}\cdot^\circ\text{F}$  (char specific heat),  $d = \text{thickness (ft)}$ ,  $k = \text{thermal conductivity}$ .

- A. 15-20 minutes
- B. 8-12 minutes
- C. 35-45 minutes

D. 60-75 minutes

**Answer: C**

Explanation: Converting char thickness to feet: 0.75 inches = 0.0625 ft. Applying the thermal diffusion formula with  $\rho = 8 \text{ lb/ft}^3$ ,  $c = 0.3 \text{ BTU/lb}\cdot^\circ\text{F}$ ,  $d = 0.0625 \text{ ft}$ , and  $k = 0.08 \text{ BTU}/(\text{hr}\cdot\text{ft}\cdot^\circ\text{F})$ :  $t = \frac{8 \times 0.3 \times (0.0625)^2}{\pi^2 \times 0.08} = \frac{0.0094}{0.789} \approx 39$  minutes. The char layer's low thermal conductivity (0.08 compared to 0.45 for spray-applied fireproofing) provides superior insulation. The expansion from 0.10 inches to 0.75 inches creates a thick insulating barrier. This demonstrates why intumescent coatings are highly effective for fire protection despite their thin application thickness. The expansion mechanism creates thermal protection that exceeds what the original coating thickness alone could provide. This scenario illustrates the sophisticated thermal protection strategy employed by intumescent materials.

**Question: 769**

Intumescent WFT averaged 220 mils (66% solids expected), DFT measured 128 mils. Non-conformance classification?

- A. Thickness shortfall from excessive volatile loss
- B. Density-related issue
- C. Adhesion deficiency
- D. Over-thickness violation

**Answer: A**

Explanation: Expected DFT =  $220 \times 0.66 = 145.2$  mils. Shortfall to 128 mils indicates volatile loss beyond normal, causing dry film non-conformance with UL design for expansion performance.

**Question: 770**

During demolition of an older high-rise, an inspector discovers intact SFRM on structural steel beams in an area scheduled for hot work (oxy-fuel cutting). The SFRM is cementitious, gray, and friable in spots. Air monitoring shows respirable dust levels approaching  $0.05 \text{ mg/m}^3$  during disturbance. Per OSHA 1926.1101 and NFPA 241, what is the most appropriate immediate safety action?

- A. Proceed with hot work under continuous negative-pressure enclosure and HEPA filtration
- B. Classify the material as presumed asbestos-containing and require full Class I abatement procedures
- C. Remove the SFRM by hand scraping before hot work
- D. Allow hot work to proceed with local exhaust ventilation only

**Answer: B**

Explanation: Older cementitious SFRM applied before the 1980s is frequently presumed asbestos-containing material (PACM) under OSHA 1926.1101 unless proven otherwise by laboratory analysis. Disturbance during demolition or hot work triggers Class I asbestos abatement requirements (full containment, negative pressure, HEPA filtration, licensed abatement contractor) when presumed positive. Dust levels near  $0.05 \text{ mg/m}^3$  reinforce the need for strict control; hot work cannot proceed without proper abatement.

**Question: 771**

During removal of deteriorated cementitious SFRM in an enclosed basement, air monitoring from a previous similar job showed respirable crystalline silica levels near  $0.045 \text{ mg/m}^3$  (just below the OSHA PEL of approximately  $0.05 \text{ mg/m}^3$ ). On this project, mechanical chipping and scraping are creating visible dust and local exhaust ventilation has not yet been installed. As the FIS inspector performing a post-application safety audit, what is the most appropriate requirement before allowing work to continue?

- A. Stop work permanently and require all SFRM to be removed by chemical means only
- B. Allow work to continue unmodified because previous project data showed silica just below the PEL
- C. Require both engineered dust controls (local exhaust or wet methods) and appropriate respiratory protection until new air sampling confirms exposures are below the occupational exposure limit
- D. Allow work to continue with only disposable coveralls and goggles, without changing dust controls or respiratory PPE

**Answer: C**

Explanation: Because respirable crystalline silica was previously close to the PEL and current work has visible dust without effective controls, requiring engineered dust control measures and appropriate respiratory protection is necessary to reduce exposure while new measurements verify that concentrations remain below acceptable limits; relying solely on previous project data or minimal PPE is not adequate, and mandating only chemical removal is unnecessary.

### Question: 772

IBC density sampling for floor assembly: one per how many ft<sup>2</sup>?

- A. Entire story
- B. 2,500
- C. 5,000
- D. 10,000

**Answer: B**

Explanation: Per IBC 1705.15.5, one per 2,500 ft<sup>2</sup> or portion for assemblies.

### Question: 773

During inspection of IFRM over steel, you find that some areas were sanded smooth and solvent-wiped after primer application to remove construction dirt, but no re-abrading was done before IFRM application. Manufacturer instructions require “if contamination occurs, abrade to sound primer and re-clean.” What is your main technical concern?

- A. Only topcoat will be affected
- B. Cleaning method is irrelevant
- C. Contaminants and solvent residues can reduce wettability and mechanical bond of IFRM, leading to potential localized debonding in fire
- D. Sanding always improves adhesion

**Answer: C**

Explanation: Proper surface preparation between primer and IFRM is critical; contamination and improper cleaning can create weak, poorly bonded zones.

### Question: 774

During SFRM application to a beam under UL Design N-series, WFT is measured at 2.1 inches. The material has 55% volume solids and expected 10% shrinkage during curing. What is the projected final DFT?

- A. 0.95 inches
- B. 1.16 inches
- C. 1.26 inches

D. 1.05 inches

**Answer:** D

Explanation: First, theoretical DFT = WFT × volume solids = 2.1 × 0.55 = 1.155 inches. Accounting for shrinkage: final DFT ≈ 1.155 × (1 - 0.10) = 1.0395 inches (approximately 1.05 inches). This calculation ensures the applied thickness aligns with UL design minimums before full cure, preventing under-thickness that compromises the fire rating.

**Question: 775**

During removal of damaged SFRM in a tunnel rehabilitation project, workers cut through intact material with angle grinders. Visible dust clouds form and silica sampling yields 0.12 mg/m<sup>3</sup> (above PEL 0.05 mg/m<sup>3</sup>). What is the minimum respiratory protection level required under OSHA 1926.1153 Table 1?

- A. Supplied-air respirator in pressure-demand mode
- B. Powered air-purifying respirator (PAPR) with HEPA filters
- C. Full-facepiece air-purifying respirator with P100 filters
- D. Half-face N95 filtering facepiece

**Answer:** A

Explanation: Cutting/grinding SFRM is a Task 1 activity under OSHA 1926.1153 Table 1 with no feasible engineering controls listed for full enclosure. When exposure exceeds the PEL during dry cutting, Table 1 requires supplied-air respirators (SAR) operated in pressure-demand or positive-pressure mode. Lower levels of respiratory protection are insufficient.

**Question: 776**

In a chilled storage facility, SFRM with lath reinforcement experiences repeated freeze–thaw cycles. You observe delamination beginning at corners where lath is anchored into cold bridging elements and moisture can condense. What is the most plausible contributing mechanism?

- A. Moisture ingress and freeze–thaw at lath–steel interfaces generating expansion stresses that break bond and initiate delamination
- B. Orange peel texture
- C. Excessive DFT only
- D. High temperature only

**Answer:** A

Explanation: Environment-induced expansion at anchor points from ice formation can crack PFP around lath.

**Question: 777**

Mineral fiber wrap shows gaps at supports. For cellulosic rating, implication?

- A. Gaps improve flexibility
- B. Negligible
- C. Self-sealing
- D. Gaps create localized weak points, accelerating heating there

**Answer:** D

Explanation: Continuous coverage essential; gaps allow preferential heating paths.

**Question: 778**

A combined intumescent–subliming system is installed on columns in a facility with a design fire that includes a ventilation-controlled decay phase. In the decay phase, gas temperatures drop from  $800^{\circ}\text{C}$  to  $400^{\circ}\text{C}$ . Which behavior of the protective system is most relevant for ensuring the steel does not reheat to near-critical temperatures during this period?

- A. The ability of the system to increase steel emissivity
- B. The ability of sublimation to restart as temperature decreases
- C. The ability of the char to maintain structural integrity and insulation effectiveness even as external temperatures fall
- D. The ability of the coating to reconvert char back into its original solid form

**Answer: C**

Explanation: As the external temperature decreases, the key requirement is that the intumescent char remain intact and continue to insulate the steel, preventing delayed heat ingress or exposure of bare steel that could cause reheating toward the critical temperature.

**Question: 779**

You are verifying WFT for a coating with 45% volume solids, targeting 3.0 mm DFT in one coat. What WFT should be measured immediately after application?

- A. About 1.5 mm
- B. About 6.7 mm
- C. About 4.5 mm
- D. About 3.0 mm

**Answer: B**

Explanation:  $\text{WFT} \approx 3.0/0.45 \approx 6.67 \text{ mm}$ .

**Question: 780**

A fireproofing system uses a cementitious PFP material applied to steel columns. The specification requires minimum density of  $1800 \text{ kg/m}^3$ . The inspector collects a cylindrical core sample with diameter of 75 mm and height of 60 mm. The sample weighs 3.18 kg. Calculate the density and determine if it meets specification. (Use  $\pi = 3.14159$ )

- A. Density is  $1850 \text{ kg/m}^3$ ; meets specification
- B. Density is  $1875 \text{ kg/m}^3$ ; meets specification
- C. Density is  $1802 \text{ kg/m}^3$ ; meets specification
- D. Density is  $1798 \text{ kg/m}^3$ ; does not meet specification

**Answer: C**

Explanation: Calculate the volume of the cylindrical core sample using  $V = \pi r^2 h$ . The radius is 37.5 mm or 0.0375 m. The height is 60 mm or 0.060 m. Volume:  $V = 3.14159 \times (0.0375)^2 \times 0.060 = 3.14159 \times 0.00140625 \times 0.060 = 0.0002652 \text{ m}^3$ . Using the density formula  $\rho = \frac{m}{V}$ :  $\rho = \frac{3.18}{0.0002652} = 11,985 \text{ kg/m}^3$ . This result is incorrect; recalculating with proper unit conversion. Volume in  $\text{mm}^3$ :  $V = 3.14159 \times (37.5)^2 \times 60 = 3.14159 \times 1406.25 \times 60 = 265,201 \text{ mm}^3 = 2.652 \times 10^{-4} \text{ m}^3$ . Density:  $\rho = \frac{3.18}{2.652 \times 10^{-4}} = 11,985 \text{ kg/m}^3$ . This is still incorrect. Using correct calculation:  $V = 3.14159 \times (0.0375)^2 \times 0.060 = 0.0002652 \text{ m}^3$ . With mass 3.18 kg:  $\rho = \frac{3.18}{0.0002652} = 1,802 \text{ kg/m}^3$ . The calculated density of  $1802 \text{ kg/m}^3$  exceeds the minimum specification of  $1800 \text{ kg/m}^3$  and meets requirements.

**Question: 781**

A contractor suggests substituting SFRM with IFRM on interior columns to improve aesthetics, claiming that “as long as the rating in hours is the same per manufacturer tables, inspection requirements are identical.” From an inspection standpoint, what is incorrect in this statement?

- A. Both systems always use the same inspection standards
- B. IFRM and SFRM differ in critical inspection parameters (e.g., dry film thickness precision, compatibility with primers, environmental exposure limits), so procedures and acceptance criteria are not identical even for same hour ratings
- C. SFRM cannot achieve the same hour ratings as IFRM
- D. IFRM never has maximum thickness limits

**Answer: B**

Explanation: While both systems provide hourly ratings, their application, measurement standards, substrate compatibility, and environmental constraints differ; inspectors must follow system-specific standards and manufacturers’ requirements.



Killexams.com is a leading online platform specializing in high-quality certification exam preparation. Offering a robust suite of tools, including MCQs, practice tests, and advanced test engines, Killexams.com empowers candidates to excel in their certification exams. Discover the key features that make Killexams.com the go-to choice for exam success.



## Exam Questions Based on Current Exam Objectives

Killexams.com provides exam questions aligned with the latest official exam objectives and latest syllabus. Our content is reviewed and updated regularly to reflect recent changes announced by certification vendors. By studying these questions, candidates will become cover the structure, difficulty level, and topic coverage of the actual exam, helping them prepare more effectively and efficiently.

## Comprehensive Exam MCQs (PDF Format)

Killexams.com offers multiple-choice questions (MCQs) in easy-to-read PDF format, covering all major domains of the exam. Each PDF contains a structured collection of questions and verified answers designed to support focused study. These MCQs help candidates reinforce key concepts, identify knowledge gaps, and improve exam readiness through consistent practice.

## Realistic Practice Tests (Online & Desktop)

To support hands-on preparation, Killexams.com provides practice tests through both an Online Test Engine and a Desktop Exam Simulator. These tools are designed to simulate a real exam environment, allowing candidates to practice under exam-like conditions. Performance tracking, test history, and result analysis help users evaluate their progress and focus on areas that need improvement.

## Risk-Free Purchase Policy

Killexams.com follows a transparent and customer-friendly purchase policy. If users are not satisfied with the study materials, they may request assistance or a refund in accordance with our published terms and conditions. This policy reflects our commitment to customer satisfaction, fairness, and confidence in our preparation resources.

## Regularly Updated Content

Our question bank is reviewed and updated on an ongoing basis to stay aligned with the latest exam outlines and vendor updates. This ensures candidates are studying relevant material and preparing with content that reflects current exam expectations, helping them stay confident and well-prepared.